



**Les Équipements Qué-Mont inc.**

7475 Boul. Thimens

St-Laurent, Qc H4S 2A2

**ASCOT** Member of the  
Ascot Corporation

**TÉL. :** (514) 331-0302

**FAX :** (514) 745-3109

**FAX :** (888) 745-3109

**WATTS** 1-800-361-1932


**Email :** [info@quemont.com](mailto:info@quemont.com)

## Breakdown

# Parts List For Tire Bead Breaker


## BB1825 BEAD BREAKER

Max. Capacity: 13.8 Ton At 10,000 PSI



ITEM NO	PART NO.	STOCK NO.	NO. DESCRIPTION	DESCRIPTION
1	16060	10606	1	Ram Half Coupler with Dust Cap
2	11000-002	45054YE3	1	Replacement Cylinder (see page 2)
3	11000-003	260154	1	Decal
4	11000-004	58448YE3	1	Frame
5	11000-005	34184	1	Set Screw
6	11000-006	28705	1	Pressure Nut
7	11000-007	36958	1	Hook
8	11000-008	22469	1	Set Screw (3/4 dia. X 2 - 1/4 Lg.; Torque to 40/60 ft. lbs.)
9	11000-009	58449YE3	1	Clevis
10	11000-010	DA11816049	1	Retaining Ring

## REPLACEMENT CYLINDER



ITEM NO	PART NO	STOCK NO.	NO. REQ'D	DESCRIPTION
11	11000-011	11127	1	Fitting Plug (3/8 NPTF)
12	11000-012	44857	1	Body, Cylinder
13	11000-013	10020	1	Soc. Hd. Cap Screw (1/4-20 x 1-1/4)
*14	11000-014	201429	1	Wiper
15	11000-015	351115	1	Guide, Rod
16	11000-016	421142	1	Rod, Piston
17	11000-017	207798	1	Bearing, Piston
*18	11000-018	207796	1	U Cup
*19	11000-019	207797	1	Retainer, Clip
20	11000-020	13654	1	Ring, Retainer (External)
21	11000-021	202625	1	Spring (.83 OD x 5.00 x 13 WS)
*22	11000-022	10442	2	Washer, Copper (.37 x .25)
23	11000-023	16064	1	Soc. Hd. Cap Screw (1/4-20 x 3-1/2)

\* Items included in the 11000-RK Repair Kit.